

# SERVICE BULLETIN

RELEASED: 1-5-98  
 REVISED: 1-10-12  
 REV: 00  
 BULLETIN: #1-98  
 FORM: 4273-2

## FILTER & SWIVEL CHANGES

MODELS AFFECTED: 65030-X-B, 636087-B

Changes affect models manufactured after Jan. 1, 1998.

The material filters used in these models are no longer available and a new connector must be used with the new filter design.

**NOTICE:**

- On “-B” models the new filter is not compatible and will not function with the “old design” connector. The “new design” connector is approximately 5/32” longer to accommodate the longer filter.
- An “A” model filter (units m’f’d prior to 1983) can no longer be replaced thru Aro, neither the “new design” filter nor connector are compatible. \* “A” models can be identified by a copper gasket located between the body and the connector.

### OLD DESIGN

| MODEL #   | FILTER # |
|-----------|----------|
| 65030-5-B | 65809-5  |
| 65030-9-B | 65809-9  |
| 636087-B  | 65809-5  |

### NEW DESIGN

| MODEL #   | FILTER # |
|-----------|----------|
| 65030-5-B | 67176-5  |
| 65030-9-B | 67176-9  |
| 636087-B  | 67167-5  |

PN 97999-1591

**INGERSOLL RAND COMPANY LTD**

209 NORTH MAIN STREET – BRYAN, OHIO 43506

(800) 495-0276 • FAX(800) 892-6276

© 2012 CCN 46734984

www.ingersollrandproducts.com

# ARO

**IR** Ingersoll Rand  
 Industrial Technologies